RFI VA246-13-B-0628 B7 Project

- Is there lead Paint in Bldg 7 in associated work areas?
 NO lead paint in area
- Who will remove and store work out equipment in 1011 Wellness?
 The VA will remove and store Equipment from the Wellness Center. A notice will be required a several weeks prior notice.
- 3. Will contractor be responsible for removing floor mounted toilets, the associated notes only indicate wall mounted accessories?
 The contractor is responsible for the removal and reinstallation of the water closets,

The contractor is responsible for the removal and reinstallation of the water closets, lavatories etc... in each restroom or bathroom.

4. Will VAMC remove low voltage items (fire alarm associated items, wireless devices, ect.) in ACT?

This will be responsibility of the contractor to remove from ceiling and leave intact so not disrupt services for each item.

5. Who is responsible for removal and storage of furniture and equipment in common areas such as the front entrance and corridors? The VA will remove all furniture as required

6. Room 1011 shows that it is to have new flooring installed. Has this area been tested for asbestos and if so, is there a report for this area?

There is no asbestos mastic in the room 1011. See attached drawing. "A"


7. On the plans, pg. 3, corridor 1 is listed three times. Are all three areas corridor 1 or has this been mislabeled?

Drawing is correct all indicate the entire area as Corridor 1

- 8. Handrail is not listed for corridor 1. Is this correct or does corridor 1 get handrails also?

 Corridor 1 is to get Handrail. This was just left off the finish schedule.
- Corridor 2 is not listed on page 3 of the drawings.
 It is located on the inside of the wellness center the, small section with VP 1 and VP 2 flooring. See drawing "B"
- 10. For page 2R of the drawings, can plans be issued with room numbers to determine specific sample areas for asbestos?
 Page 2R is shown with the area and room number of the specific area of the samples taken. The area shown is the only area that is being removed
- 11. On page 2R, Sample #'s 13-7-1-04, 13-7-1-05, 13-7-1-18, 13-7-1-19, and 13-7-1-20 are not indicated on the plans. Can you show where these sample numbers are located so that abatement can be figured accurately?

Those are offices which is not included in the scope of the abatement. The only abatement is to be in the main corridor and the two little corridors.



DRAWING A QUESTION 6

